

Montclair Board of Education  
 Drinking Fountain Survey 2016 - 2017 School Year  
 Northeast School

Location	Type	Test by Township of Mtc - Date	Test by Township of Mtc - Results	Detail Associates Test Date	Detail Associates Test Results	Detail Associates Test Date	Detail Associates Test Results	Detail Associates Test Date	Detail Associates Test Results	Detail Associates Test Date	Detail Associates Test Results	Comments
Hall by Room 22	Drinking Fountain	3/11/16	<2 ug/L			10/14/16	<3 ppb					
Cooler by Kitchen	Cooler	3/11/16	<2 ug/L									
Kitchen	Sink	3/11/16	<2 ug/L									
Hall by room 32	Drinking Fountain			8/2/16	None detected							
Rm 30 on sink	Drinking Fountain			8/2/16	None detected							
Rm 32 on sink	Drinking Fountain			8/2/16	None detected							
Room 34	Drinking Fountain			8/2/16	None detected							
Rm 28	Drinking Fountain			8/2/16	None detected							
Hall by Room 13 & 14	Drinking Fountain			8/2/16	None detected	10/14/16	<3 ppb			12/26/16	BDL	
by Elevator Ground Floor	Drinking Fountain					10/14/16	<3 ppb					
Rm 33 on sink	Drinking Fountain			8/2/16	None detected	10/14/16	<3 ppb					
by Rm 28	Drinking Fountain			8/2/16	1 ppb	10/14/16	<3 ppb					
Rm 27	Drinking Fountain			8/2/16	2 ppb	10/14/16	<3 ppb					
Rm 26	Drinking Fountain			8/2/16	2 ppb	10/14/16	<3 ppb					
Nurse Office	Sink							11/16/16	BDL			
Room 25	Drinking Fountain			8/2/16	1 ppb	10/14/16	3.89 ppb			12/28/16	BDL	
Teachers Room	Sink									5/17/17	BDL	
Room 14	Drinking Fountain			8/2/16	12 ppb	not working				not working		Unit shut down
Room 13	Drinking Fountain			8/2/16	8 ppb	not working				not working		Unit shut down

Footnote: BDL refers to Below detectable limits.